Apple II Technical Notes



Developer Technical Support

Apple IIGS

#7: Halt Mechanism in IIGS SANE

Revised by: Guillermo Ortiz & Matt Deatherage November 1988
Written by: Guillermo Ortiz December 1986

This Technical Note formerly described a bug of SANE on the Apple IIGS which caused it to jump through location \$00/0018 instead of through the HALT vector in the SANE direct page.

The bug which caused SANE on the Apple IIGS to jump through location \$00/0018 instead of through the HALT vector in the SANE direct page was fixed in the Apple IIGS ROM 2.0. You should not have to write a special case to handle this bug since it is reasonable to expect users to have the updated ROM which is offered as a free upgrade from Apple.